

TRAIL ASSESSMENT FORM

Doc. #		Trail Name	Glover Path	Trail Type:	M	Condition	Good
Route:	Trail starts heading SE at intersection with Slide Hill Trail Marker 3040 ending at Hawk Hill Path Marker 3044.						
Recent Weather:	Overcast and cold, about an inch or rain the previous day						
TRAIL LANDMARKS	<p>Start at Slide Hill Trail Marker 3040.</p> <p>70 yds. NE side: remains of building foundation?</p> <p>85 yds. Tree down and across trail, 14" pine (1)</p> <p>300 yds. Trail crosses stone wall then slopes down, minor erosion. Possible site for grade reversal just after stone wall (2).</p> <p>350 yds. Next few 100' trail climbs again, moderate erosion. Good location for grade reversal to get water off the trail (3).</p> <p>380 yds. Trail crosses 2nd stone wall.</p> <p>510 yds. Trail levels and begins to slope down.</p> <p>563 yds. Grade reversal with stone showing, L to R, could use more dirt to cover stones.</p> <p>593 yds. Trail ends at Hawk Hill Path Marker 3044.</p>						
MINOR & MAJOR PROBLEM AREAS	<p>(1) Tree down, needs to be removed.</p> <p>(2) Possible site for grade reversal. Install (2) and determine if this second one is necessary.</p> <p>(3) Install grade reversal about 30 yds. before 2nd stone wall.</p>						
DISTANCES TO MAJOR INTERSECTIONS	<ul style="list-style-type: none"> Slide Hill Trail Marker 3040 to Hawk Hill Path - 593 yds. 						
Report prepared by:	Bob Flagg			Assessment date:	01/12/16		

TRAIL ASSESSMENT FORM

Doc. #	3018	Trail Name	Glover Path	Trail Type:	M	Condition	Good
Route:	From mk3044 at Hawk Hill Trail(HHT) to Slide Hill Trail at mk3040						
Recent Weather:	Recent storm/rain/high winds conditions						
TRAIL LANDMARKS	<p>Trail starts at mk3044 HHT first in a northerly heading and follows the contour of HHT eventually towards NW. Trail is for the most part a well-designed bench trail with no drainage issues.</p> <p>235yd rock wall crossing(on old FoBH map)</p> <p>355yd another rock wall crossing(on old FoBH map)</p> <p>523 sbd carry-off</p> <p>593yd mk3040 no mk(1) trail ends at Slide Hill Trail</p>						
MINOR PROBLEM	(1) replace mk						

AREAS	
MAJOR PROBLEM AREAS	
DISTANCES TO MAJOR INTERSECTIONS	593yd mk3044 HHT to Slide Hill Trail at mk3040
Report prepared by:	Steve Cobble
Assessment date:	02/21/08

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)
culverts(cv)	large blowdowns (lbd)
rolling dips (rd)	rock work (rkw)
bridges (br)	bridge building (bbd), ditches (dt)
excessive erosion (ee)	leaning tree (lt)
intersection marker(mk)	dugout(du)
bog bridges (bb)	culvert replacement (cr)
non-functioning(nf)	functioning(fc)
damage(dg)	corrugated plastic(cp)
not needed(nn)	
cm (corrugated metal)	
rock stairs (rs)	trail relocation (tr),
cribbing (cb)	building new trail drainage (ntd)
retaining walls (rw)	brushing needed (bn)
clay(cl)	