

## TRAIL ASSESSMENT FORM

<b>Doc. #</b>		<b>Trail Name</b>	Laurel Path	<b>Trail Type:</b>	M	<b>Condition</b>	Good
<b>Route:</b>	From the southern boundary fence at Rt 93 to Bouncing Brook Path						
<b>Recent Weather:</b>	Sunny and cold, 1" of rain the previous day						
<b>TRAIL LANDMARKS</b>	<p>Wide trail starts at the southern fence at Rt 93</p> <p>105 yds Intersection with Braintree Pass Path coming in on L</p> <p>250 yds Intersection with Hemlock Bound Trail on R</p> <p>337 yds 18" clay culvert, L to R, could use good clean to remove leaves on inflow, water flowing</p> <p>350 yds Intersection with Barberry Bush Spring Trail on L at Marker 3121</p> <p>Laurel Path turns R and descends at this point towards the edge of a swampy hemlock area. Water used to flow from Barberry but this has been corrected with grade reversals on Barberry</p> <p>365 yds Intersection with the end of Hemlock Bound Trail coming in on R</p> <p>510 yds dugout on L side, trail follows swamp on R</p> <p>733 yds stone culvert, L to R, water flowing</p> <p>743 yds 16" clay culvert, L to R, water flowing</p> <p>753 yds Intersection with Great Dome Foot Path at Marker 3111 on L.</p> <p>Corrugated steel culvert, not functioning, on surface of treadway, not needed and could be removed.</p> <p>756 yds culvert, water flowing, can't find inflow</p> <p>.60 mi. swale 4' wide (max), water flowing L to R, drains into the hemlock stand</p> <p>.61 mi. 24" clay culvert, L to R, water flowing</p> <p>.62 mi. Intersection with Bouncing Brook Path</p>						
<b>MINOR/MAJOR PROBLEM AREAS</b>	None						
<b>DISTANCES TO MAJOR INTERSECTIONS</b>	<ul style="list-style-type: none"> <li>• Fence at Rt 93 to Braintree Pass Path - 105 yds.</li> <li>• Fence at Rt 93 to Barberry Bush Spring Trail Marker 3121 - 350 yds.</li> <li>• Fence at Rt 93 to Great Dome Foot Path Marker 3111 - 105 yds.</li> <li>• Fence at Rt 93 to Bouncing Brook Path - .62 mi.</li> </ul>						
<b>Report prepared by:</b>	Bob Flagg			<b>Assessment date:</b>	01/17/16		