

TRAIL ASSESSMENT FORM

Doc. #	1026	Trail Name	Valley Path South	Trail Type:	Wide - M	Condition	Good
Route:		Intersection marker 1224 to paved road					
Recent Weather:		Rainy today – No snow on trail					
TRAIL LANDMARKS		<ul style="list-style-type: none"> Valley Path South trailhead leaves the Border Path north on the left at intersection marker 1224, .17 miles north of Hillside Street. Minor erosion at start of trail caused by run off from the treadway and hill. Two water sampling standpipes to the left of treadway at 170 feet. This erosion continues up the hill as the treadway is the low point between two hills. The erosion could be better controlled by ditching the treadway as appears to be done partially either naturally or engineered. (1) Bn at 388 feet. Bn at .14 miles. Bn at .15 miles. Bn at .17 miles. Bn at .18 miles. Bn at .2 miles. Sbd across treadway at .21 miles. Valley Path ends with its intersection with a paved road that connects Hillside Street with Unquity Road at .25 miles. 					
MINOR PROBLEM AREAS		<ul style="list-style-type: none"> Minor erosion continues up the hill as the treadway is the low point between two hills. The erosion could be better controlled by ditching the treadway as appears to be done partially either naturally or engineered. (1) 					
MAJOR PROBLEM AREAS		<ul style="list-style-type: none"> None noted 					
DISTANCES TO MAJOR INTERSECTIONS		<ul style="list-style-type: none"> Border Path intersection marker 1224 – to paved road. - .25miles 					
Report prepared by:		Ken Jones			Assessment date:		2/5/2008

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)
culverts(cv)	large blowdowns (lbd)
rolling dips (rd)	rock work (rkw)
bridges (br)	bridge building (bbd),
bog bridges (bb)	culvert replacement (cr)
rock stairs (rs)	trail relocation (tr),
cribbing (cb)	building new trail drainage (ntd)
retaining walls (rw)	brushing needed (bn)

ditches (dt)

excessive erosion (ee)

leaning tree (lt)