

TRAIL ASSESSMENT FORM

Doc. #	3008	Trail Name	Curve Path	Trail Type:	M	Condition	Good
Route:		Mk3130 at BBT to 3153 at Wampatuck Path(Trail) .37 mi					
Recent Weather:		1" snow covering some portions of trail, some icy spots, no precip past 7 days					
TRAIL LANDMARKS		mk3130 4' wide trail with some washout and water flow, probably due to misdirected stream and drainage 174 yd cv cp diag exposed(1) 214 yd mk3135 int with Sassaman Notch Trail on NW side. Curve Trail starts NE bearing and trail widens. 404 yd mk3143 'triangle' int with Squamaug Notch Trail. Trail turns left at triangle, and quick right, after triangle. Some washout coming down from N off Squamaug Notch Trail . Follows a perennially wet area on S side that needs some attention in the form of a rd or outsloping investigate 659 yd mk3153 int w/ Wampatuck Trail					
MINOR PROBLEM AREAS		(1) cv and drainage needs cleaning and possibly reset—above grade and could be a hazard This would alleviate most of the washout.					
MAJOR PROBLEM AREAS							
DISTANCES TO MAJOR INTERSECTIONS		659 yd/.37 mi. from BBT mk3130 to mkWampatuck 3153					
Report prepared by:			Steve Cobble		Assessment date:		01/23/08

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb) culverts(cv) rolling dips (rd) bridges (br) excessive erosion (ee) intersection marker(mk) bog bridges (bb) non-functioning(nf) damage(dg) not needed(nn) cm (corrugated metal) rock stairs (rs) cribbing (cb) retaining walls (rw) clay(cl)	small blowdowns (sbd) large blowdowns (lbd) rock work (rkw) bridge building (bbd), ditches (dt) leaning tree (lt)) dugout(du) culvert replacement (cr) functioning(fc) trail relocation (tr), building new trail drainage (ntd) brushing needed (bn)
--	--

corrugated plastic(cp)