TRAIL ASSESSMENT FORM

Doc. #	3018A	Trail N	ame	Glover Path	Trail Type:	М	Condition	Good	
Route:			Trail starts heading SE at intersection with Slide Hill Trail ending at mk						
			3044, (Hawk Hill Trail).						
Recent	Weather:		Sunny, cool, dry. Much leaf debris on trail.						
TRAII	TRAIL			Start at Slide Hill Trail. bn at start of trail.					
LANDMARKS			Minor bn along first 1000' trail bed very good here.						
				NE side: remains of b	uilding foundat	ion?			
				bn small white pines	. 11.4	1 1			
				' upslope levels off at		-			
				' sbd (bowsaws). Poss few 100' trail climbs					
				wall. Install wb or 2.	agam, mouerau		Tall Closses	2	
				from end of trail (mk	3044) trail leve	els and begi	ns to slope (down	
				com end, install wb.	50 m), dui iev		no to stope v	10 W II.	
				ends at mk 3044, mee	ets Hawk Hill T	rail.			
MINO	MINOR		Erosion significant at 3044 and moderate near stone walls.						
PROBLEM									
AREA	AREAS								
MAJO	R								
PROBLEM									
AREA	S								
DISTA	NCES '	ГО							
MAJO	R								
INTER	SECTI	ONS							
Report	Report prepared by:			aleb Blankenship	Asses	sment date	e: 11/7/09		

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)
culverts(cv)	large blowdowns (lbd)
rolling dips (rd)	rock work (rkw)
bridges (br)	bridge building (bbd),
bog bridges (bb)	culvert replacement (cr)
rock stairs (rs)	trail relocation (tr),
cribbing (cb)	building new trail drainage (ntd)
retaining walls (rw)	brushing needed (bn)
ditches (dt)	excessive erosion (ee)
	leaning tree (lt)

TRAIL ASSESSMENT FORM

Doc. #	3018	Trail N	lame	Glover Path	Trail Type:	М	Condition	Good	
Route:			From mk3044 at Hawk Hill Trail(HHT) to Slide Hill Trail at mk3040						
Recent Weather:			Recent storm/rain/high winds conditions						
TRAIL			Trail starts at mk3044 HHT first in a northerly heading and follows the						
LANDMARKS			contour of HHT eventually towards NW. Trail is for the most part a well-						
		designed bench trail with no drainage issues.							
		235yd rock wall crossing(on old FoBH map)							
		355yd another rock wall crossing(on old FoBH map)							
		523 sbd carry-off							
			593yd mk3040 no mk(1) trail ends at Slide Hill Trail						
MINOR			(1) replace mk						
PROBLEM									
AREAS									
MAJOR									
PROBLEM									
AREAS									
DISTANCES TO		593yd mk3044 HHT to Slide Hill Trail at mk3040							
MAJOR									
INTERSECTIONS									
Report prepared by:			St	eve Cobble	Asses	sment date	e: 02/21/08		

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)
culverts(cv)	large blowdowns (lbd)
rolling dips (rd)	rock work (rkw)
bridges (br)	bridge building (bbd), ditches (dt)
excessive erosion (ee)	leaning tree (lt))
intersection marker(mk)	dugout(du)
bog bridges (bb)	culvert replacement (cr)
non-functioning(nf)	functioning(fc)
damage(dg)	corrugated plastic(cp)
not needed(nn)	
cm (corrugated metal)	
rock stairs (rs)	trail relocation (tr),
cribbing (cb)	building new trail drainage (ntd)
retaining walls (rw)	brushing needed (bn)
clay(cl)	