

TRAIL ASSESSMENT FORM

Doc. #	3021A	Trail Name	Savoy Path	Trail Type:	M	Condition	Good
Route:		Trail marker 3030 at Hawk Hill Path to Rte. 28					
Recent Weather:		Overcast, cool, wet.					
TRAIL LANDMARKS		Start at tr mk 3030 heading down slope, water flowing down trail 50 yds. Need to replace wb 70 yds. bn 200 yds. Good spot for wb or rd 210 yds. Good spot for wb or rd 250 yds bn 300 yds. Trail on map intersects on north side of trail– no name. bn 400 yds. br 450 yds. trail ends at Rte. 28.					
MINOR PROBLEM AREAS		Need to construct 2 or 3 wb or rd to get water off of trail. Needs a good brushing esp. from 250 yds. to end. Trail end at Rte. 28 tends to be a magnet for illegal dumping.					
MAJOR PROBLEM AREAS							
DISTANCES TO MAJOR INTERSECTIONS							
Report prepared by:			Caleb Blankenship		Assessment date:		11/29/09

TRAIL ASSESSMENT FORM

Doc. #	3021	Trail Name	Savoy Path	Trail Type:	M	Condition	Good
Route:		Starting at Hawk Hill Trail mk3030, heading S/SW, to rte.28					
Recent Weather:		Clear, 1-2" snow on ground					
TRAIL LANDMARKS		64.6yd nf nn wb bn 295yd mk3012 no mk(1)unnamed trail enters from N 419yd du 431yd br 449yd. stone entrance rte 28 kiosk w/map					
MINOR PROBLEM AREAS		(1) Install mk					

MAJOR PROBLEM AREAS	none		
DISTANCES TO MAJOR INTERSECTIONS	Mk3030 to rte 28 trailhead 449yd		
Report prepared by:	Steve Cobble	Assessment date:	03/3/08

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)	
culverts(cv)	large blowdowns (lbd)	
rolling dips (rd)	rock work (rkw)	
bridges (br)	bridge building (bbd), ditches (dt)	corrugated plastic(cp)
excessive erosion (ee)	leaning tree (lt))	
intersection marker(mk)	dugout(du)	
bog bridges (bb)	culvert replacement (cr)	
non-functioning(nf)	functioning(fc)	
damage(dg)		
not needed(nn)		
cm (corrugated metal)		
rock stairs (rs)	trail relocation (tr),	
cribbing (cb)	building new trail drainage (ntd)	
retaining walls (rw)	brushing needed (bn)	
clay(cl)		