

TRAIL ASSESSMENT FORM

Doc. #	3023	Trail Name	Streamside Edge Path	Trail Type:	M	Condition	Good
Route:		Heading generally S from mk3072 at intersection with Braintree Pass Path and Hawk Hill Path, to the fence along rte128 at mk3060 then E to Branch Path					
Recent Weather:		Clear, no recent precip.					
TRAIL LANDMARKS		Wide trail begins at mk3072 at intersection with Braintree Pass Path and Hawk Hill Path 458yd mk3066(mk3060 on DCR map)(1) 490yd nf cv not an issue heading downhill, trail has some drainage issues(2) 571yd mk3061(3) Hemlock Bound Foot Path crosses after this intersection, same issues(2) 739yd lt(4) .58mi trail turns left(E) after dike(?). Old FoBH map shows this as mk3060 Trail follows the rte128 fence through a perennially wet area, tread is dry .66mi stream under wooden br still pretty solid, may need work in a 1-2 years .73mi. trail ends at Branch Path					
MINOR PROBLEM AREAS		(1) need to correct signage or map (2) recommend some drainage correction here maybe in the form of rd (3) need mk (4) chainsaw					
MAJOR PROBLEM AREAS							
DISTANCES TO MAJOR INTERSECTIONS		458yd mk3072 to mk3066 571yd mk3072 to mk3061 .58mi mk3072 to mk 3060 .73mi mk3072 to end at Branch Path					
Report prepared by:			Steve Cobble		Assessment date:		03/10/08

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)
culverts(cv)	large blowdowns (lbd)
rolling dips (rd)	rock work (rkw)
bridges (br)	bridge building (bbd), ditches (dt)
excessive erosion (ee)	leaning tree (lt)
intersection marker(mk)	dugout(du)
bog bridges (bb)	culvert replacement (cr)
non-functioning(nf)	functioning(fc)
damage(dg)	retaining walls (rw)
not needed(nn)	brushing needed (bn)
cm (corrugated metal)	clay(cl)
rock stairs (rs)	trail relocation (tr),
cribbing (cb)	building new trail drainage (ntd)

corrugated plastic(cp)