

TRAIL ASSESSMENT FORM

Doc. #	3024	Trail Name	Branch Path	Trail Type:	M	Condition	Good
Route:		From end of Streamside Edge Path(SEP) N to mk3066(3060?) at SEP					
Recent Weather:		Clear, no recent precip					
TRAIL LANDMARKS		Trail begins at southern end of SEP 354yd possible cv under causeway no issues 384yd mk3071 Hemlock Bound Foot Path crosses 537yd some drainage issues with waterflow on trail recommend rd and/or ditch with armored water crossing at this point. Not a big issue 607yd mk3066 trail ends at SEP					
MINOR PROBLEM AREAS		Trail is in good shape except where noted					
MAJOR PROBLEM AREAS							
DISTANCES TO MAJOR INTERSECTIONS		607yd loop from S end of SEP, to mk3066 at SEP					
Report prepared by:			Steve Cobble		Assessment date:		03/10/08

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb) culverts(cv) rolling dips (rd) bridges (br) excessive erosion (ee) intersection marker(mk) bog bridges (bb) non-functioning(nf) damage(dg) not needed(nn) cm (corrugated metal) rock stairs (rs) cribbing (cb) retaining walls (rw) clay(cl)	small blowdowns (sbd) large blowdowns (lbd) rock work (rkw) bridge building (bbd), ditches (dt) leaning tree (lt)) dugout(du) culvert replacement (cr) functioning(fc) trail relocation (tr), building new trail drainage (ntd) brushing needed (bn)
--	--

corrugated plastic(cp)