

TRAIL ASSESSMENT FORM

Doc. #	2009	Trail Name	Monatiquot Path	Trail Type:	M(MTB)	Condition	Good
Route:		Mk2190 at Bugbee/Forest path intersection, along the fenced border, to the base					
Recent Weather:							
TRAIL LANDMARKS		33yd unused trail on left recommend DCR take off map 132yd trail crosses Pipeline 340yd trail makes a sharp right, narrows, and proceeds down towards the fenced park border .57mi trail turns right onto Old 128 and ends at base of Pipeline. No mk There are two trail 'difficulty' signs on a post in the trees adjacent to the rte.128 fence, which is confusing. Recommend either removing or placing the two signs where they can be more visible and useful.					
MINOR PROBLEM AREAS		None					
MAJOR PROBLEM AREAS		None					
DISTANCES TO MAJOR INTERSECTIONS		From mk2190: 132yd to Pipeline .57mi to end at S end of Pipeline					
Report prepared by:			Steve Cobble		Assessment date:		04/18/08

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb) culverts(cv) rolling dips (rd) bridges (br) excessive erosion (ee) intersection marker(mk) bog bridges (bb) non-functioning(nf) damage(dg) not needed(nn) cm (corrugated metal) rock stairs (rs) cribbing (cb) retaining walls (rw) clay(cl) MTB(mountainbikes allowed) (mk2042) meaning not on DCR map	small blowdowns (sbd) large blowdowns (lbd) rock work (rkw) bridge building (bbd), ditches (dt) leaning tree (lt)) dugout(du) culvert replacement (cr) functioning(fc) corrugated plastic(cp) trail relocation (tr), building new trail drainage (ntd) brushing needed (bn)
---	--