

TRAIL ASSESSMENT FORM

Doc. #	2018	Trail Name	Tucker Hill Path	Trail Type:	M(MTB)	Condition	Good
Route:		From Headquarters Path, generally south, starting just north of mk2081, crossing the Skyline, to mk2070, and down the paved 'picnic loop' to the bottom at (mk2063)					
Recent Weather:		Clear and dry					
TRAIL LANDMARKS		Wide trail begins at Headquarters Path no mk green dot loop and white arrows 47yd old wb nn 123yd mk2081 Athol Path crossing 376yd (2072) (Ayer Trail) 389yd Skyline crossing 545yd old Massachuseck trail crosses 555yd mk2070 int with Bugbee. Tucker Hill Path bears right and becomes paved road. 950yd no name trail left(mk2053) 970yd end of trail					
MINOR PROBLEM AREAS		No issues					
MAJOR PROBLEM AREAS							
DISTANCES TO MAJOR INTERSECTIONS		123yd to Athol path 555yd to mk2070 970yd to end					
Report prepared by:			Steve Cobble		Assessment date:		05/12/08

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)
culverts(cv)	large blowdowns (lbd)
rolling dips (rd)	rock work (rkw)
bridges (br)	bridge building (bbd), ditches (dt)
excessive erosion (ee)	leaning tree (lt))
intersection marker(mk)	dugout(du)
bog bridges (bb)	culvert replacement (cr)
non-functioning(nf)	functioning(fc)
damage(dg)	
not needed(nn)	
cm (corrugated metal)	
rock stairs (rs)	trail relocation (tr),
cribbing (cb)	building new trail drainage (ntd)
retaining walls (rw)	brushing needed (bn)
clay(cl)	
MTB(mountainbikes allowed)	
(mk2042) meaning not on DCR map	