

TRAIL ASSESSMENT FORM

Doc. #	2024	Trail Name	Athol Path	Trail Type:	H	Condition	Good
Route:		From Headquarters Path just east of Blue Hills Headquarters					
Recent Weather:		Clear and dry					
TRAIL LANDMARKS		Where trail begins at HQ Path the entrance is undefined and overgrown 100yd mk2081 crossing Tucker Hill Path 521yd path on right Skyline connector 546yd trail ends at top of Tucker Hill					
MINOR PROBLEM AREAS		None					
MAJOR PROBLEM AREAS							
DISTANCES TO MAJOR INTERSECTIONS		From HQ Path: 100yd to Tucker Hill Path 546yd to end					
Report prepared by:			Steve Cobble		Assessment date:		05/21/08

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)	
culverts(cv)	large blowdowns (lbd)	
rolling dips (rd)	rock work (rkw)	
bridges (br)	bridge building (bbd), ditches (dt)	corrugated plastic(cp)
excessive erosion (ee)	leaning tree (lt))	
intersection marker(mk)	dugout(du)	
bog bridges (bb)	culvert replacement (cr)	
non-functioning(nf)	functioning(fc)	
damage(dg)		
not needed(nn)		
cm (corrugated metal)		
rock stairs (rs)	trail relocation (tr),	
cribbing (cb)	building new trail drainage (ntd)	
retaining walls (rw)	brushing needed (bn)	
clay(cl)		
MTB(mountainbikes allowed)		
(mk2042) meaning not on DCR map		