TRAIL ASSESSMENT FORM

Doc. #	2033	Trail N	lame	AMC Footpath South	Trail Type:	Narrow – H	Condition	Poor Route Finding	
Route:			Unnamed path – 2194 – 2182 - 2165						
Recent Weather:			Sunny in the 40's. – No precipitation last 48 hours						
TRAIL LANDMARKS			• Trailhead is located off of an Unnamed path that parallels Chickatawbut Road, .1 miles east of intersection marker 2175 at its closest point to Chickatawbut Road. Intersection maker 2175 is accessed via a road width path directly across from Forest Street at a granite marker labeled Forest						
]	Path. • Although the locati DCR map, it is still reflect this as the A walk.	on of this footp shown as an un MC Footpath.	ath is shown nnamed trail. This trail is a	on the latest Future maps wonderful w	(9/09) will oodland	
			• The AMC Footpath leaves this unnamed trail on the right (south) at a small partially buried boulder, bordered by small old downed limbs. This trailhead as well as several sections of this trail should be better identified. Downed leaves may have hampered route finding. The treadway was lost several times during the assessment and if it were not for the help of several worn orange circular blazes, the assessment could not have been completed. (1)						
			• (Overhead bn immediat	ely leaving the	trailhead.			
		• Sbd crosses the treadway at 41 feet with overhead bn continuing.							
		• Sbd crosses the treadway at 170 feet.							
		Treadway becomes difficult to follow at 380 feet. Faded orange circular							
		blazes are noted. Tied surveyor tape on tree.							
			• ′	Treadway crosses a roc	ck wall at .16 m	iles.			
			•	 Treadway enters Forres At this point the Altreadway as the Forright (S) at footpath 	MC footpath tur rrest Path for ap	rns left (SE) a proximately	and shares the 20 feet. It the	e same en turns	
			•	.18 miles. Treadway begins to cl					
				following faded orange		Č		-	
				Treadway again becom blazes. (2)	nes difficult to f	ollow at .22 1	miles. Need n	nore	
			• ′	Treadway continues as	a deer trail thro	ough .27 mile	es.		
			• (Overhead bn at .29 mil	es.				
				Side and Overhead bn					
			1	Treadway enters an int marker 2182 at .33 mil opposite side of Buck I continuing to ascend at	es. The AMC I Hill Path at the it footpath width	Footpath cont no mountain	tinues south o biking placar	on the	
				Bn at .37 miles. Pine b	•	-	<u> </u>	0**	
				SBD crosses the tready diameter.	•	-			
				Freadway begins to en Freadway enters a clea			_		

	beautiful views of Ponkapoag Pond.			
	• Unnamed path leaves on the left (east) from this rock outcropping while			
	the AMC Footpath continues straight (south).			
	• Treadway enters another clearing with a large rock outcropping at .48			
	miles.			
	• From this rock outcropping, the AMC Footpath continues straight			
	(southwest) on a lightly traveled path through scrub with bn.			
	 Additionally, from this rock outcropping, an obvious well-worn unnamed path leaves on the left (southeast) to the summit cairn of 			
	Buck Hill in .03 miles.			
	• Unnamed trail leaves on the left to summit at .49 miles.			
	Treadway becomes almost non-discernable with significant brushing			
	required at .50 miles.			
	• Treadway is lost in heavy scrub at .52 miles. Had to bushwhack a heading			
	of 240 degrees magnetic to the visible intersection marker 2165 to regain			
	footpath. (3)			
	• The treadway from .48 miles through .53 miles is in need of major			
	brushing. Treadway would not be navigable during the summer			
	months in this area. Decision needs to be made whether to perform this extensive brushing to portray the treadway as shown on the map			
	or to ascend Buck Hill the way people currently do from the well			
	traveled footpath leaving the rock outcropping at .48 miles.			
	Scrub reenters the AMC Footpath just prior to a large boulder and ends at			
	the Skyline Trail at intersection marker 2165 at .53 miles.			
MINOR	None noted			
PROBLEM				
AREAS				
MAJOR	1. The AMC Footpath leaves this unnamed trail on the right (south) at a			
PROBLEM	small partially buried boulder, bordered by small old downed limbs. This			
AREAS	trailhead as well as several sections of this trail should be better identified.			
	Downed leaves may have hampered route finding. The treadway was lost			
	several times during the assessment and if it were not for the help of			
	several worn orange circular blazes, the assessment would not have been completed. (1)			
	2. Treadway again becomes difficult to follow again at .22 miles. Need			
	additional blazes. (2)			
	3. Treadway is lost in heavy scrub at .52 miles. Had to bushwhack a heading			
	of 240 degrees magnetic to the visible intersection marker 2165 to regain			
	footpath. (3)			
	• The treadway from .48 miles through .53 miles is in need of major			
	brushing. Treadway would not be navigable during the summer			
	months in this area. Decision needs to be made whether to perform this extensive brushing to portray the treadway as shown on the map			
	or to ascend Buck Hill the way people currently do from the well			
	traveled footpath leaving the rock outcropping at .48 miles.			
DISTANCES TO	Trailhead to Forrest Path at intersection marker 219417 miles			
MAJOR	• Trailhead to Buck Hill Path at intersection marker 218233 miles			
INTERSECTIONS	Trailhead to Skyline Trail at intersection marker 2165 at .53 miles.			
Report prepared by:	Ken Jones – 11/26/2009 Assessment date: 11/24/2009			

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb) small blowdowns (sbd) culverts(cv) large blowdowns (lbd)

rolling dips (rd) rock work (rkw)
bridges (br) bridge building (bbd),
bog bridges (bb) culvert replacement (cr)
rock stairs (rs) trail relocation (tr),

cribbing (cb) building new trail drainage (ntd)

retaining walls (rw) brushing needed (bn) ditches (dt) excessive erosion (ee)

leaning tree (lt)