## TRAIL ASSESSMENT FORM

Doc. #	5003		Γrai	l Name	Acton Path West Revision 1	Trail Type:	Wide - M	Condition	Good		
Pouto:				Pas	ervetion Roundary route	24 5305	Swamp Trail	5321 5175	<u> </u>		
Recent Weather:					Reservation Boundary route 24 – 5395 –Swamp Trail – 5321 - 5175  Rain last 24 hours. Cloudy in the 30's						
Route: Recent TRAII LAND				Rain	Trailhead is located at the route 24 highway fence area of the gas pipeline surveyor tape.  Hemlock Road crosses area of the gas pipeline surveyor tape.  Hemlock Road crosses are a portion of the control of the contr	in the 30's he reservation. Treadway a and is blazed at 225 feet. ion the treadway in the treadway at .37 mill yay at .41 mill way at .71 mill way at .75 mill way at .75 mill way at .77 mill	m boundary and this point is to a control of the right a way at .2 miles way at .24 miles way at .29 miles at the Swamp Tood footpath lead At this point A control of the second	d leaves from he heavily brind left with best. Steel 24" pies. Corrugated pies. Corrugated pies. Corrugated pies. DT needs at the pipeline the south side es. L to R. Sipe. Dt on both white PVC pies. Wearthen try well on leave well on leave well on leave to left of tree.	pe. pipe. pipe. pipe. pipe. pipe. porthe ft ares the ad west PVC PVC to the e of th sides ipe. ft. ft.		
				•	Dt ascending hill to left	of treadway	from .77 throu	igh .83 miles.	•		
					Cv crosses under tready construction w/12" correleft.	ugated PVC	pipe. Clean en	try, exit and			
					Unnamed path enters or road to the AMC Camp Unnamed path enters or	s entering at	a fire gate onto	Randolph S	treet.		
					fire gate onto Randolph	Street.					
					Runoff in the treadway location. (1) See photo	pgdl1.					
					Treadway enters an inte miles. This is the main o						

	limited parking.					
	<ul> <li>Overhead bn at 1.02 miles w/ dt noted to the left of the treadway from</li> </ul>					
	intersection.					
	• Cv crosses under treadway at 1.03miles. L to R. Rkw/earthen					
	construction w/12" corrugated PVC pipe. Clean debris from right.					
	• Rock wall crossing to the left and right of the treadway at 1.06 miles.					
	• Cv crosses under treadway at 1.08 miles. L to R. Rkw/earthen					
	construction. Pipe <sup>3</sup> / <sub>4</sub> full with debris. Clean entry, exit and dt on left.					
	• Cv crosses under treadway at 1.25 miles. L to R. No entry or exit noted.					
	<ul> <li>Corrugated steel pipe protruding from treadway.</li> <li>Two cv cross under treadway at 1.33 miles. L to R. Rkw/earthen/cement</li> </ul>					
	construction. Corrugated steel 15"pipe and with another smaller pipe.					
	Clean entry, exit and dt. New stone dust on top of treadway.					
	• Cv crosses under treadway at 1.35 miles. L to R. 12" corrugated steel					
	pipe crushed on left. Clean entry, exit and dt on left. Needs additional dt					
	on left to reduce runoff in the treadway (2).					
	• Rock wall crossing to the left and right of the treadway at 1.4 miles.					
	• Unnamed path enters on the left at 1.46 miles with blue diamond blaze					
	<ul> <li>5230 nailed to tree.</li> <li>Two unnamed paths enter on the left at road width, cross to pond then U</li> </ul>					
	turn and return at 1.6 miles.					
	<ul> <li>Treadway enters a narrow road width path at 1.67 miles with the pond</li> </ul>					
	to the right, wetland to the left and a wonderful view of Great Blue Hill.					
	• Large cv under the treadway at 1.71 miles at pond outlet. Concrete					
	spillway to right of treadway.					
	• Treadway enters an intersection with the golf course at intersection					
	marker 5175 at 1.83 miles. At this point there is a fire gate where the					
	Acton Path ends. Crossing the fire gate, Maple Avenue enters on the left. The Redman Farm Path begins here leaving on the right (north)					
	while continuing to follow the green blazes through the golf course to					
	the west of Ponkapoag Pond.					
	•					
MINOR	1. Runoff in the treadway at .91 miles. 2-3 inches deep. Possible cv					
PROBLEM	location. (1) See photo pgdl1.					
AREAS	2. Cv crosses under treadway at 1.35 miles. Pipe crushed on left. Needs					
MAJOR	<ul><li>additional dt on left to reduce runoff in the treadway (2).</li><li>None noted</li></ul>					
PROBLEM	- None noted					
AREAS						
DISTANCES TO	Route 24 reservation boundary to Hemlock Road - 225 feet					
MAJOR	<ul> <li>Route 24 reservation boundary to Helmock Road - 223 reet</li> <li>Route 24 reservation boundary to the Swamp Trail (FBH map)35</li> </ul>					
INTERSECTIONS	miles.					
HALLINGECHOINS	• Route 24 reservation boundary to entry road to the AMC Camps85					
	miles					
	• Route 24 reservation boundary to Fishermans Beach at intersection					
	marker 532197 miles.					
	Route 24 reservation boundary to Acton Path ends at intersection  marker 5175 1 83 miles					
Report prepared by:	marker 5175 - 1.83 miles.  Ken Jones – 4/12/08 <b>Assessment date:</b> 4/7/2008					
report prepared by.	13011 JUHOS = 4/12/00   ASSESSMENT UATE:   4/1/2000					

pgdl1:



## **Abbreviations:**

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb) small blowdowns (sbd)
culverts(cv) large blowdowns (lbd)
rolling dips (rd) rock work (rkw)
bridges (br) bridge building (bbd),
bog bridges (bb) culvert replacement (cr)
rock stairs (rs) trail relocation (tr),

cribbing (cb) building new trail drainage (ntd)

retaining walls (rw) brushing needed (bn) ditches (dt) excessive erosion (ee)

leaning tree (lt)