## TRAIL ASSESSMENT FORM

	• Culvert, steel 24", exposed, under the treadway at .66 miles. R to L. Working well.			
	Sassaman Path Marker 4048 enters on right at .74 miles.			
	Pine Tree Brook Path Marker 4049 enters on right at .75 miles.			
	Ditch running in the center of the treadway from .73 through .75 miles. Exits right on path.			
	• Pleasant Trail enters at Marker	Pleasant Trail enters at Marker 4046 at .78 miles.		
	<ul> <li>Stone swale at .79 miles.</li> <li>Headquarters Path ends with its intersection with the pipeline at .82 miles. Signage at this point requests that hikers "Please Keep of the Gas</li> </ul>			
	Pipeline and Use the Trails".			
MINOR&MAJOR	1. Side ditch at .53 miles should be repaired to direct water to culvert			
PROBLEM	under trail.			
AREAS	. Side ditch crossing Pasture Run at .58 miles should be repaired to keep			
	water off Headquarters Path. Need to make sure proper water flow is maintained in side path for about twenty feet.			
DISTANCES TO	<ul> <li>Chickatawbut Road to Cedar Rock Path Marker 401255 miles.</li> </ul>			
MAJOR	Chickatawbut Road to Pasture Run Trail Marker 403058 miles.			
INTERSECTIONS	<ul> <li>Chickatawbut Road to Sassaman Path Marker 404874 miles.</li> <li>Chickatawbut Road to Pine Tree Brook Path Marker 404975 miles.</li> <li>Chickatawbut Road to Pleasant Trail Marker 404678 miles.</li> </ul>			
INTERSECTIONS				
	<ul> <li>Chickatawbut Road to Headquarters Path end at the pipeline82</li> </ul>			
	miles.			
<b>Report prepared by:</b>	Bob Flagg	Assessment date:		