

## TRAIL ASSESSMENT FORM

<b>Doc. #</b>		<b>Trail Name</b>	Cliff Trail	<b>Trail Type:</b>	Footpath	<b>Condition</b>	Good
<b>Route:</b>	Summit Road to Coon Hollow Path Marker 1082						
<b>Recent Weather:</b>	Warm, 50's - melting snow and ice – Snow cover on trail less than 1 inch. Trail a bit muddy from snow melt.						
<b>TRAIL LANDMARKS</b>	<ul style="list-style-type: none"> <li>• Trail starts Summit Road and is part of the Red Dot Loop. Sign for the summit of Blue Hills.</li> <li>• Trail heads uphill over a series of telephone pole waterbreaks for .06 miles. There are clear signs the water flows down this trail as there is no place for the water to run on either side of the trail.</li> <li>• Telephone pole waterbar at .02 miles is only opportunity to get water off the trail. There is a culvert that runs under Summit Road so a good cleaning of this waterbar will allow the water to flow under the road instead of flowing down the road. (1)</li> <li>• Small blowdown at .06 miles which can be cleared with a bow saw.</li> <li>• Another series of telephone pole waterbreaks between .11 and .13 miles. Small pond on left side of trail. This drains to a side ditch on Coon Hollow Path.</li> <li>• Trail ends at Coon Hollow Path at .25 miles.</li> </ul>						
<b>MINOR&amp;MAJOR PROBLEM AREAS</b>	(1) The water runs down this trail almost unimpeded. Need to clean waterbar at .02 miles get water off the trail to culvert under the road.						
<b>DISTANCES TO MAJOR INTERSECTIONS</b>	<ul style="list-style-type: none"> <li>• Summit Road to Coon Hollow Path Marker 1082 – .25 miles.</li> </ul>						
<b>Report prepared by:</b>	Bob Flagg			<b>Assessment date:</b>	2/2/16		