

TRAIL ASSESSMENT FORM

Doc. #		Trail Name	Romari Trail	Trail Type:	Narrow	Condition	Good
Route:	Wood Path Marker 3174, heading southwest along the park boundary, ends at Bouncing Brook Path.						
Recent Weather:	Sunny in the 30s						
TRAIL LANDMARKS	<ul style="list-style-type: none"> • Access from Wood Road gate at Wood Path. • Trail starts at about 70 yards in on Wood Path (heading west) on the left. • The map shows this trail as perfectly straight, running along the park boundary for ¼ mi. It does meander some, with slight rolling hills. • Mostly hard pack terrain, but some technical with loose rocks on the hilly sections. • Biggest landmarks are the industrial businesses on the SE side of the trail that can be seen and heard from most of the trail. • 8 ft. plywood and 3" x 3" stringer bridge with flowing water 141 yds from start. Should replace bridge within a couple years as plywood is starting to separate. (1) • 12" concrete culvert at same point carrying stream under industrial parking lot. • Monitoring well just off trail at 230 yds. looks to be relatively recent addition. Wetlands area just to the right of trail. • Rockwork culvert behind industrial parking lot at 257 yds. The culvert on the SE side of the trail is approx 10 yards back from the trail, draining perpendicular to trail). Wood stakes, test pipe, and 'wetland deliniation' flags at same point • Trail ends at Bouncing Brook Path behind an industrial park Quonset hut at 370 yds. 						
MINOR&MAJOR PROBLEM AREAS	(1) Bridge at 141 yds could be replaced in the next two years with a more appropriate structure.						
DISTANCES TO MAJOR INTERSECTIONS	<ul style="list-style-type: none"> • Wood Path Marker 3174 to Bouncing Brook Path - 370 yds. 						
Report prepared by:	Bob Flagg			Assessment date:	3/20/16		