

# TRAIL ASSESSMENT FORM

<b>Doc. #</b>		<b>Trail Name</b>	Streamside Edge Path	<b>Trail Type:</b>	M	<b>Condition</b>	Good
<b>Route:</b>		Heading generally S from Marker 3072 at intersection with Braintree Pass Path and Hawk Hill Path, to the fence along Rt. 128 then E to Branch Path					
<b>Recent Weather:</b>		Overcast and cold, about an inch or rain the previous day					
<b>TRAIL LANDMARKS</b>		<p>Wide trail begins at marker 3072 at intersection with Braintree Pass Path and Hawk Hill Path</p> <p>458 yds. Intersection with Branch Path at Marker 3066</p> <p>490 yds. Stone culvert, R to L</p> <p>heading downhill, trail has some drainage issues(2)</p> <p>.58 mi. trail turns L (E) after dike (?). Trail follows the Rt. 128 fence through a perennially wet area, tread is dry</p> <p>.66 mi. stream under wooden bridge still pretty solid</p> <p>.73 mi. trail ends at Branch Path</p> <p><b>Note:</b> Hemlock Bound Foot Path has been decommissioned E from Marker 3030 so there is no longer any signage at the old intersection.</p>					
<b>MINOR &amp; MAJOR PROBLEM AREAS</b>		None					
<b>DISTANCES TO MAJOR INTERSECTIONS</b>		<ul style="list-style-type: none"> <li>• Braintree Pass Path Marker 3072 to Branch Path Marker 3066 - 458 yds.</li> <li>• Braintree Pass Path Marker 3072 to end at Branch Path near Rt. 128 - .73 mi.</li> </ul>					
<b>Report prepared by:</b>		Bob Flagg			<b>Assessment date:</b>		01/12/16