

## TRAIL ASSESSMENT FORM

<b>Doc. #</b>		<b>Trail Name</b>	Buck Hill Trail	<b>Trail Type:</b>	Medium	<b>Condition</b>	Good
<b>Route:</b>	Forest Path, heading generally SW, following the S contours of Buck Hill, to Doe Hollow Path						
<b>Recent Weather:</b>	Raining, 50's						
<b>TRAIL LANDMARKS</b>	<ul style="list-style-type: none"> <li>• Trail starts at Forest Path heading uphill</li> <li>• 106 yds wooden waterbar, R to L, needs to be reestablished, water flowing over structure (1)</li> <li>• 127 yds wooden waterbar, R to L, needs to be reestablished, water flowing over structure (2)</li> <li>• 171 yds Skyline Trail Marker 2210 crosses trail. Red Dot joins trail and follows same trail.</li> <li>• .18 mi Buck Hill Path Marker 2183 enters R.</li> <li>• .45 mi Fern Spring Foot Path Marker 2162 crosses. Trail starts to descend fall line with significant erosion in some sections.</li> <li>• .50 mi grade reversal, R to L, needs to be reestablished (3)</li> <li>• .51 mi grade reversal, L to R, needs to be reestablished (4)</li> <li>• .52 mi grade reversal, R to L, clean</li> <li>• .55 mi grade reversal, R to L</li> <li>• .56 mi wooden waterbar, R to L, clean</li> <li>• .60 mi 8" clay culvert, R to L, clean. Seasonal stream crossing, culvert empties onto swale on Fells Path.</li> <li>• .61 mi Fells Path Marker 2152 leaves L.</li> <li>• .64 mi stone enhanced grade reversal, R to L. Add dirt to cover rocks.</li> <li>• .65 mi Trail ends at fork at Doe Hollow Path. Red Dot continues to L.</li> </ul>						
<b>MINOR&amp;MAJOR PROBLEM AREAS</b>	<ol style="list-style-type: none"> <li>(1) Need to reestablish grade reversal by digging out trench in front of structure and cleaning outflow ditch</li> <li>(2) Need to reestablish grade reversal by digging out trench in front of structure and cleaning outflow ditch</li> <li>(3) Need to reestablish grade reversal by digging out trench in front of structure and cleaning outflow ditch</li> <li>(4) Need to reestablish grade reversal by adding stones to grade reversal, digging out trench in front of structure and cleaning outflow ditch</li> </ol>						
<b>DISTANCES TO MAJOR INTERSECTIONS</b>	<ul style="list-style-type: none"> <li>• Forest Path to Skyline Trail Marker 2210 - 171 yds</li> <li>• Forest Path to Buck Hill Path Marker 2183 - .18 mi</li> <li>• Forest Path to Fern Spring Foot Path Marker 2162 - .45 mi</li> <li>• Forest Path to Fells Path Marker 2152 - .61 mi</li> <li>• Forest Path to Doe Hollow Path - .65 mi</li> </ul>						
<b>Report prepared by:</b>	Bob Flagg			<b>Assessment date:</b>	4/2/16		