

## TRAIL ASSESSMENT FORM

<b>Doc. #</b>		<b>Trail Name</b>	Sassaman Path	<b>Trail Type:</b>	Wide	<b>Condition</b>	Good
<b>Route:</b>		Pasture Run - 4047 – 4048					
<b>Recent Weather:</b>		Overcast, 40's, 1" rain yesterday					
<b>TRAIL LANDMARKS</b>		<ul style="list-style-type: none"> <li>• Sassaman Path leaves from the east side of the Pasture Run approximately 1/8 of a mile north of Chickatawbut Road.</li> <li>• Treadway enters a 4-way intersection at .17 miles. Intersection not obvious on map. It is actually that Sassaman and Ridge alongside each other. Ridge Path enters on right and continues on right while Sassaman Path enters on left and continues left. This intersection could have appropriate signage installed to eliminate confusion.</li> <li>• At .20 miles, treadway begins descending into an area of runoff and minor erosion that continues to the Pipeline. Need to install grade reversal to get water off the trail. <b>(1)</b></li> <li>• Ridge Path enters on the right at Marker 4047 at .23 miles.</li> <li>• Sassaman Path ends Headquarters Path Marker 4048 at .29 miles.</li> </ul>					
<b>MINOR&amp;MAJOR PROBLEM AREAS</b>		1. Water flows down center of trail around .20 miles and continuing onto Headquarters Path. Need to install grade reversal, R to L, to get water off the trail at the earliest point on the trail. Trail has high edges so need to find first available location.					
<b>DISTANCES TO MAJOR INTERSECTIONS</b>		<ul style="list-style-type: none"> <li>• Trailhead to 4 way intersection - .17 miles. Sassaman Path enters on left and continues on left.</li> <li>• Trailhead to Ridge Path Marker 4047 - .23 miles.</li> <li>• Trailhead to Headquarters Path Marker 4048 - .29 miles.</li> </ul>					
<b>Report prepared by:</b>		Bob Flagg		<b>Assessment date:</b>		3/16/16	