TRAIL ASSESSMENT FORM

and stone surround. Ditch on left and debris at inflow. Culvert under treadway at mile 1.35. L to R with 26" black plastic pipe and earthen/stone surround construction. ½ full of debris. Unnamed path leaves on right around Little Dome at 1.45 miles. Indian Camp Path leaves on left at intersection marker 4083 at 1.59 miles. Trail enters the Pipeline at intersection marker 4066 at 1.69 miles. Pipeline and the Sawcut Notch use the same treadway for approximately 50 yards and then Sawcut Notch leaves on the right at 1.71 miles. Signage at this point notes the CCC Camp to the west and the Chickatawbut overlook to the south. Stone grade reversal at mile 1.73, good condition. Stone grade reversal at mile 1.75, good condition. Ditch on the right of the treadway and leaving at 1.79 miles. Culvert under treadway at mile 1.94. 20" cement pipe runs R to L with stone surround construction. Very little flow and 1/3 full of debris. Minor erosion noted at 1.96 miles. Evidence that runoff is crossing trail. Culvert under treadway in streambed at 1.99 miles. R to L. Rockwork and earthen walls with 15" dia. pipe. Unnamed path leaves on right at 2.09 miles. CCC trail leaves on left at intersection marker 4042 at 2.14 miles. Signage at this point notes the CCC Camp to the south, Chickatawbut to the east and Randolph Ave to the west. CCC trail reenters on the left at 2.34 miles, intersection marker 4014. Ditch to right of treadway into culvert at 2.35 miles. Clay pipe 15". 1/4 full of debris on right, buried on left. Heavy cleaning required. (4) Two culverts under treadway at 2.45 miles. One in streambed R to L w/ 30" corrugated pvc pipe. Other culvert is rockwork. Entries and exits are clear on both. Note lots of poison ivy surrounding both culverts. Sawcut Notch Path ends at Randolph Avenue at a fire gate and granite marker at 2.55 miles, intersection marker 4011. Granite marker is labeled Sawcut Notch Path. Reservation map board as well as CCC signage is located at this point. Trail from this point in to Intersection marker 4042 is blazed with a yellow triangular CCC blaze. No parking is available on Randolph Ave. (1) Culvert under the treadway at .16 miles. Heavily impacted .12" dia. pipe MINOR&MAJOR half full of debris on left. No outlet could be found on right. Investigate **PROBLEM** AREAS (2) Culvert under treadway at .25 miles. Could not locate inlet or outlet in rockwork. Investigate. (3) Blowdown protruding into trail at .75 miles. 14" diameter. Needs chainsaw. (4) Ditch to right of treadway into culvert at 2.35 miles. Clay pipe 15". 1/4 full of debris on right, buried on left. Heavy cleaning required. Wampatuck Road to Skyline Trail and intersection marker 4214 - .1 miles. Wampatuck Road to Old Furnace Brook Path at intersection marker

DISTANCES TO MAJOR INTERSECTIONS

- 4180 .51 miles.
- Wampatuck Road to Short Path 1.00 miles
- Wampatuck Road to Indian Camp Path intersection marker 4083 1.59 miles.

	Wampatuck Road to the Pipeline at intersection marker 4066 - 1.69 miles. Wampatuck Road to Unnamed path at intersection marker 4042 - 2.14 miles.		
	Wampatuck Road to Randolph Avenue - 2.55 miles.		
Report prepared by:	Sterling Dintersmith	Assessment date:	5/10/16