

# Friends of the Blue Hills

## Trail Volunteer Work Report

**Work date (mm/dd/yy):** 8/19/10

**Report date:** 08/19/2010

**Your name:** Ray Ajemian

**List Volunteers working with you:**

0

**Trail Name:** Border Path

**Section Name/Description:**

1175 to Unquity Road

**Work Completed (Please be specific with location of work. Note hazards & potential hazards addressed if applicable):**

- 1) Cleared and lowered dirt around seven water bars
- 2) Trimmed some brushes
- 3) Cleared large rocks from path

**Total Hours (# of people x hours worked):** 1:00

**Work Remaining:**

. See below

**Other comments (areas of concern, wildlife sightings, trail markings and signage condition, need for re-route, possible encroachment):**

Although the path on the surface is in good shape, there is an ongoing problem which will require a lot of work. Water from the intersection of four paths (1175) flows directed down the Border Path (have watched it in very wet weather). The first water bar cannot contain the water and it overflows to other water bars. The problem is that the first section (1175 to first water bar) is becoming rutted and full of rocks. For a hiker it is not much of a problem, but for a biker, it can be a problem.

I would suggest that the section be looked at with the possibility of working on the intersection at 1175 at some point in the future. As it is right now, I can continue to clean the waterbars, that one section is going to get worse.

Forward completed electronic form to: Dexter Robinson @ [dexpcdoc@gmail.com](mailto:dexpcdoc@gmail.com)