

# Friends of the Blue Hills

## Trail Volunteer Work Report

**Work date (mm/dd/yy):** 4/5/10

**Report date:** 4/6/10

**Your name:** Bob Vogel

**List Volunteers working with you:**

N/A

**Trail Name:** Five Corners Path

**Section Name/Description:**

Entire

**Work Completed (Please be specific with location of work. Note hazards & potential hazards addressed if applicable):**

Cut back greenbrier along start of trail, and assorted other places along trail. Picked up fallen sticks. Brushed a few places where branches and small shrubs were growing into trail.

**Total Hours (# of people x hours worked):** 2.00

**Work Remaining:**

There was still quite a bit of water on the trail in a couple places. From just above 1140 most of the way to 1135 people have been walking off trail to keep out of the water.

Also, at the junction of 1135, the past heavy rains have done serious damage to the Five Corners Path. When I adopted the trail there was a 'hole' at this intersection, caused by water running down Five Corners Path. I had done some work, and was keeping it under control. This past storm caused a major washout. There is now a ditch 2' across and 18" deep, right in the middle of the trail at the junction. To 'solve' this problem will require creating a waterbar to get the water off the trail before this intersection. I believe that attempting to continuously fill the ditch will prove unsuccessful unless something is done to eliminate the flowing water.

**Other comments (areas of concern, wildlife sightings, trail markings and signage condition, need for re-route, possible encroachment):**

Forward completed electronic form to: Dexter Robinson @ [dexpdoc@gmail.com](mailto:dexpdoc@gmail.com)