

Friends of the Blue Hills

Trail Volunteer Work Report

Work date (mm/dd/yy): 3/17/13

Report date: 3/17/13

Your name: Caleb Blankenship

List Volunteers working with you:

N/A

Trail Name: Border Path

Section Name/Description:

Blue Hill Section/near trail marker 1214

Work Completed (Please be specific with location of work. Note hazards & potential hazards addressed if applicable):

Re-established partial flow in the large, formerly non-functioning culvert at the bottom of Hemenway Hill. Constructed a make-shift weir using two large white pine logs and a large stone to direct some of the water into the culvert. Cleared the outflow end of the culvert of leaves and downed branches.

Total Hours (# of people x hours worked): 1.00

Work Remaining:

A more permanent, more effective weir must be installed.

Other comments (areas of concern, wildlife sightings, trail markings and signage condition, need for re-route, possible encroachment):

Much of the water from Chestnut Run continues to by-pass the twin culverts and further wash out a large section of the trail.

Forward completed electronic form to: Dexter Robinson @ dexpcdoc@gmail.com