

TRAIL ASSESSMENT FORM

Doc. #		Trail Name	Pipsissewa Path	Trail Type:	Wide	Condition	Good
Route:	South from intersection with Hemenway Hill Path						
Recent Weather:	Sunny, 45°F, all day rain on previous day						
TRAIL LANDMARKS	<ul style="list-style-type: none"> • 397ft erosion from uphill side – culvert or swale? • Did not see intersection with Hancock Trail • 0.17mi reaches Unquity Rd 						
MINOR PROBLEM AREAS	<ul style="list-style-type: none"> • Needs brushing – many white pines along trail 						
MAJOR PROBLEM AREAS	<ul style="list-style-type: none"> • Obvious water issue coming from uphill side – best action might be a swale to limit erosion 						
DISTANCES TO MAJOR INTERSECTIONS	<ul style="list-style-type: none"> • 0ft Hemenway Hill Path • ? Hancock Trail • 0.17mi Unquity Rd at Intersection 1208 (sign is across the road) 						
Report prepared by:	Robert Shine			Assessment date:	10-23-2016		