

TRAIL ASSESSMENT FORM

Doc. #		Trail Name	Summit Trail	Trail Type:	Wide	Condition	Good
Route:	From Wolcott Path heading East						
Recent Weather:	Sunny, 45°F, all day rain on previous day						
TRAIL LANDMARKS	<p>Starting at intersection with Wolcott Path (West to East)</p> <ul style="list-style-type: none"> • 0ft have 16in concrete culvert –could use cleaning • 303ft side ditch to initial culvert needs deeping • 425ft side ditch stops • 477ft black 12in exposed plastic culvert completely blocked downtrail (unfound) uptrail has some clearance but needs cleaning • Erosion at .1mi • 0.13 mi rotted grade reversal – needs complete overall • 0.14 mi complete overhaul of grade reversal needed • 0.16 intersects with paved Summit Road 						
MINOR PROBLEM AREAS	<ul style="list-style-type: none"> • Large concrete culvert needs to be cleaned • 220ft signs of erosion – possible grade reversal • Side ditch (425 to 475 feet from Wolcott path) needs deepening 						
MAJOR PROBLEM AREAS	<ul style="list-style-type: none"> • At both 0.13 and 0.14 mi water bars need complete overhaul – suggest changing to grade reversal 						
DISTANCES TO MAJOR INTERSECTIONS	<ul style="list-style-type: none"> • Trail starts at Wolcott Path at 0ft • Ends at Summit Road at 0.16mi 						
Report prepared by:	Robert Shine			Assessment date:	10-23-2016		