

TRAIL ASSESSMENT FORM

Doc. #		Trail Name	Valley Path South	Trail Type:	Wide - M	Condition	Good
Route:		Intersection marker 1224 to paved road					
Recent Weather:		Sunny, some recent rain					
TRAIL LANDMARKS		<ul style="list-style-type: none"> • Valley Path South trailhead leaves the Border Path north on the left at intersection marker 1224, .17 miles north of Hillside Street. • Minor erosion at start of trail caused by run off from the treadway and hill. • Brushing for first 60 feet. • Two water sampling standpipes to the left of treadway at 170 feet. • This erosion continues up the hill as the treadway is the low point between two hills. The erosion could be better controlled by ditching the treadway as appears to be done partially either naturally or engineered. Would require mechanical means to make this happen. Not a high priority as trail is little used. • Valley Path ends with its intersection with a paved road that connects Hillside Street with Unquity Road at .25 miles. 					
MINOR/ MAJOR PROBLEM AREAS		None					
DISTANCES TO MAJOR INTERSECTIONS		<ul style="list-style-type: none"> • Border Path intersection marker 1224 – to paved road. - .25miles 					
Report prepared by:			Bob Flagg		Assessment date:		12/25/15