## TRAIL ASSESSMENT FORM

Doc. #	1006	Trail l	Name	Half Way path	Trail Type:	Wide Trail - M	Condition	Good		
Doutos			<b>A</b>	ad Dath 1091 100	2 1110 11	12 Househter Dot	1-			
Route:		Accord Path –1081-1093-1110- 1143 – Houghton Path								
Recent Weather:		Snow 12/2, Cloudy and cold – Partial snow coverage up to 1 inch on trail								
Recent Weather: TRAIL LANDMARKS		<ul> <li>Show 12/2, Cloudy and cold – Partial show coverage up to 1 finch on trail</li> <li>Trail is most easily accessed starting from the parking area 1/8 of a mile west from Blue Hills River Road. Follow an unnamed side path that parallels Hillside Street on the north side, west for 275 feet to the Wildcat Notch Path trailhead. Follow the Wildcat Notch Path to intersection marker 1086 (260 feet from TH), the Accord Path will leave on the left. Opportunity for signage here as 3 paths leave from this intersection. (1)</li> <li>Half Way Path Trailhead leaves the Accord Path at intersection marker 1081, .11 miles from the Wildcat Notch Path trailhead. Zero GPS</li> <li>Trail narrows and needs brushing at .0102 miles.</li> <li>Sbd crosses trail at .04 miles. 6" dia.</li> <li>Wildcat Notch Path crosses at intersection marker 1093 at .09 miles.</li> <li>Trail opens to road width and requires brushing.</li> <li>Cv for stream bed under road at .2 miles. L to R. Rkw wells with 24" dia. Cement pipe. Wb w/additional dt on left into stream All require cleaning. Note: Additional stream bed crosses trail 100 feet prior to this cv and washes over trail during high runoff times causing very minor erosion. Possible bog bridge or cv location. (2)</li> <li>Unnamed trail crosses at intersection marker 1110 At .24 miles. Five Corners Path ??</li> <li>Brushing required at .3 miles.</li> </ul>								
			<ul> <li>C</li> <li>pi</li> <li>T</li> <li>ac</li> <li>S<sup>i</sup></li> <li>W</li> <li>H</li> </ul>	oon Hollow Path c v for stream bed un pe and good dt. Re rail climbs 100 ' af Iditional wb ant dt. bd on left at .42 mi /b at .47 miles. L to alf Way Path ends oughton Path at .44	nder road at equires clea fter cv with . (3) lles. o R. Dt on r at intersect	.39 miles. L to R. ning. minor erosion note ight sweeping wat	ed. Opportuni er off trail. C	ty for lean dt.		
PROBLEM AREAS			(1) O fr (2) S du bu (3) M	<ol> <li>(1) Opportunity for signage at intersection marker 1086 as 3 paths leave from this intersection.</li> <li>(2) Streambed crosses trail at .2 miles prior to cv and washes over trail during high runoff times causing very minor erosion. Possible bog bridge or cv location.</li> <li>(3) Minor erosion noted after cv at .39 miles. Opportunity for additional wb ant dt.</li> </ol>						
MAJO PROBI AREAS DISTA	LEM S NCES	бТО	None • A	e Noted ccord/ Half Way P	Path marker	1081 to Wildcat N	otch Path ma	rker		
MAJOR INTERSECTIONS		<ul> <li>1093 – .09 miles.</li> <li>Accord/ Half Way Path marker 1081 to unnamed path marker 1110 -</li> </ul>								

	•	.24 miles Accord/ Half Way Path marker Accord/ Half Way Path marker marker 1143 48 miles		
<b>Report prepared by:</b>		Ken Jones	Assessment date:	12/7/2007

## Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)
culverts(cv)	large blowdowns (lbd)
rolling dips (rd)	rock work (rkw)
bridges (br)	bridge building (bbd),
bog bridges (bb)	culvert replacement (cr)
rock stairs (rs)	trail relocation (tr),
cribbing (cb)	building new trail drainage (ntd)
retaining walls (rw)	brushing needed (bn)
ditches (dt)	excessive erosion (ee)
	leaning tree (lt)