

TRAIL ASSESSMENT FORM

Doc. #		Trail Name	Branch Path	Trail Type:	M	Condition	Good
Route:		From end of Streamside Edge Path N to Marker 3066 at Streamside Edge Path					
Recent Weather:		Overcast and cold, about an inch or rain the previous day					
TRAIL LANDMARKS		<p>Trail begins at southern end of Streamside Edge Path</p> <p>354 yds. Treadway elevated with culvert under causeway, some leaves at inflow and outflow but no action needed, some waterflow</p> <p>537 yds. Swale with stone enhancements, L to R, some waterflow</p> <p>607 yds. Trail ends at intersection with Streamside Edge Path at Marker 3066</p> <p>Note: Hemlock Bound Foot Path has been decommissioned E from Marker 3030 so there is no longer any signage at the old intersection.</p>					
MINOR & MAJOR PROBLEM AREAS		None					
DISTANCES TO MAJOR INTERSECTIONS		South end of Streamside Edge Path to trail end intersection with Streamside Edge Path at Marker 3066 - 607 yds.					
Report prepared by:			Bob Flagg		Assessment date:		01/12/16