## TRAIL ASSESSMENT FORM

Doc. # Trail N	NameHawk Hill PathTrail Type:MConditionGood
Route:	From Rt. 28, heading generally E, to Braintree Pass Path Marker 3072
Recent Weather:	Overcast and cold, about an inch or rain the previous day
TRAIL	Rt. 28 trail starts. This is not a proper trailhead as it is blocked by a
LANDMARKS	guardrail. Map shows start of trail at Pipeline.
	Trail maintains 6-8' wide throughout.
	25 yds. Marker 3005, at intersection with Gas Pipeline
	33 yds Intersection with Pakomet Path entering from right
	170 yds. Telephone pole waterbar, L to R
	185 yds. Telephone pole waterbar, L to R
	195 yds. Telephone pole waterbar, L to R
	200 yds. dugout left
	205 yds. Telephone pole waterbar, L to R
	253 yds. Rock waterbar, L to R
	320 yds. Rock waterbar, L to R
	440 yds. southern lookout
	465 yds. Intersection on L with the terminus of Hemlock Bound Foot Path 475 yds. Intersection with Seven Path on P. et Merker 2020
	475 yds. Intersection with Savoy Path on R at Marker 3030 715 yds. Stone enhanced grade reversal, L to R
	725 yds. Intersection with Glover Path on L at Marker 3044
	765 yds. Stone enhanced grade reversal, R to L
	895 yds. Stone enhanced grade reversal, R to L
	.59 mi. 2 rock waterbreaks
	.60 mi. Stone enhanced grade reversal, R to L
	.61 mi. Path ends at intersection with Braintree Pass Path and Streamside
	Edge Path at Marker 3072
	<b>Note:</b> Hemlock Bound Foot Path has been decommissioned E from intersection at Hawk Hill near Marker 3030.
MINOR &	A grade reversal should be added about 25 – 30 yds. before two
MAJOR	waterbreaks.
PROBLEM	
AREAS	
DISTANCES TO	• Rt. 28 to Pipeline at Marker 3005 - 25 yds.
MAJOR	• Rt. 28 to Pakomet Path - 33 yds.
INTERSECTIONS	• Rt. 28 to Hemlock Bound Foot Path $-465$ yds.
	• Rt. 28 to Savoy Path at Marker 3030 - 475 yds.
	• Rt. 28 to Glover Path at Marker 3044 - 725 yds.
	Rt. 28 to Braintree Pass Path at Marker 307261 miles
<b>Report prepared by:</b>	Bob FlaggAssessment date:01/12/16