

## TRAIL ASSESSMENT FORM

<b>Doc. #</b>		<b>Trail Name</b>	Savoy Path	<b>Trail Type:</b>	M	<b>Condition</b>	Good
<b>Route:</b>	Trail Marker 3030 at Hawk Hill Path to Rte. 28						
<b>Recent Weather:</b>	Overcast and cold, about an inch or rain the previous day						
<b>TRAIL LANDMARKS</b>	<p>Start at Marker 3030 heading down slope</p> <p>50 yds. Grade reversal with stone showing, L to R</p> <p>150 yds. Grade reversal with stone showing on half the trail, L to R</p> <p>300 yds. Pakomet Path intersects on north side of trail</p> <p>400 yds. Small wooden bridge in good shape crosses small flowing stream</p> <p>450 yds. Path ends at Rte. 28. The trailhead is an old roadside pullover with stone walls constructed around 1935 by the Civilian Conservation Corp. The walls could use some repairs. The other side of the pullover is at Hawk Hill Path. There is an information board located at the trailhead.</p>						
<b>MINOR &amp; MAJOR PROBLEM AREAS</b>	The walls at the trailhead could use some masonry repairs.						
<b>DISTANCES TO MAJOR INTERSECTIONS</b>	<ul style="list-style-type: none"> <li>• Hawk Hill Path Marker 3030 to Pakomet Path - 300 yds.</li> <li>• Hawk Hill Path Marker 3030 to Rt. 28 - 450 yds.</li> </ul>						
<b>Report prepared by:</b>	Bob Flagg			<b>Assessment date:</b>	01/12/16		