

TRAIL ASSESSMENT FORM

Doc. #		Trail Name	Slide Hill Trail	Trail Type:	M	Condition	Good
Route:	Trailhead at Pipeline Marker 3013 heading NW ending at Braintree Pass Path.						
Recent Weather:	Overcast and cold, about an inch or rain the previous day						
TRAIL LANDMARKS	<p>Trailhead at Pipeline Marker 3013</p> <p>200 yds. Intersection with Bouncing Brook Path Side ditch from intersection heading E could use some cleanout for 100'. Unreadable unofficial marker located at intersection.</p> <p>370 yds. Intersection with Glover Path at Marker 3040</p> <p>510 yds. Wood waterbar that is not functioning. Outflow heads up hill so no action.</p> <p>520 yds. Trail ends at intersection with Braintree Pass Path. Side ditch on L was reconstructed to collect water from Slide Hill and divert into side ditch flowing downhill on Braintree Pass Path.</p> <p>Note: Map for trail on Resources page shows trailhead at Rt. 28. This should be corrected as this section of trail is actually part of Hemlock Bound Foot Path. It was probably changed due to the decommissioning of Hemlock Bound but Hemlock Bound is an active trail until Marker 3030.</p>						
MINOR & MAJOR PROBLEM AREAS	Correct map for trail on Resources page						
DISTANCES TO MAJOR INTERSECTIONS	<ul style="list-style-type: none"> • Pipeline Marker 3013 to Bouncing Brook Path - 200 yds. • Pipeline Marker 3013 to Glover Path Marker 3040 - 370 yds. • Pipeline Marker 3013 to Braintree Pass Path - 370 yds. 						
Report prepared by:	Bob Flagg			Assessment date:	01/12/16		