

## TRAIL ASSESSMENT FORM

<b>Doc. #</b>		<b>Trail Name:</b>	Wood Path	<b>Trail Type:</b>	Wide - H	<b>Condition</b>	Good
<b>Route:</b>	Wood Path, from gate at Wood Road, Braintree, to Wampatuck Path Marker 3157						
<b>Recent Weather:</b>	Sunny and cool, 1" of rain yesterday						
<b>TRAIL LANDMARKS</b>	<p>Trail actually starts approx. 130 yards <i>outside</i> the BH map, at a gate on Wood Road. No official parking area and deli across the street closed so no longer available for parking. I am traveling west from this point, and measurements start at the gate.</p> <p>138 yds. from the gate, Romari Path, a narrow trail, enters on L. The trail continues on fairly flat and ranges from 3 ft. to 8 ft., with approx. 3 ft. tread throughout. Interesting 'rock piles' on L of trail. R side is looking upslope with some obvious fire damage years ago. L side looks like it can be wet in season but not encroaching on the trail.</p> <p>780 yds. nick on L, could enhance to provide better drainage</p> <p>791 yds. trail takes a turn upslope with some erosion and large rocks showing which may make it harder for vehicle passage.</p> <p>900 yds. stone armored culvert with a small seasonal stream crossing with an old square beam waterbar on surface. Water had been flowing across trail along waterbar but some digging revealed culvert which is now functioning properly.</p> <p>910 yds. stone culvert runs under trail (water was flowing) but inflow is not visible. Should try to dig this out to improve flow (1)</p> <p>.62 mi. Trail meets Wampatuck Path at Marker 3157.</p>						
<b>MINOR/MAJOR PROBLEM AREAS</b>	(1) Review inflow area of culvert at 910 yds. to enhance flow.						
<b>DISTANCES TO MAJOR INTERSECTIONS</b>	Wood Road to Wampatuck Path Marker 3157 - .62 mi.						
<b>Report prepared by:</b>	Bob Flagg			<b>Assessment date:</b>	01/17/2016		