TRAIL ASSESSMENT FORM

Doc. # 3010 Trail N	lame	Carve Path	Trail Type:	Н	Condition	Good
Route:	mk3065 to BPP at mk3036, 490 yd					
Recent Weather:	Heavy rainstorm last night					
TRAIL	Trail starts off Skyline bearing SW from near the Education Center fe					
LANDMARKS	Chick. Hill. at mk 3065(1)					
	33 yd scenic overlook on left					
	bn needed entire length, a lot of smaller blowdown branches, etc.					
	121 yd 2sbd(2)					
	450 yd trail takes a sharp left down to BBT					
	(The trail at this point seems to proceed straight)					
	450 yd mk3051 at BBT					
	Trail crosses BBT					
	458 yd sbd(3)					
	yd trail ends at BPP					
MINOR	(1) mk missing, replace					
PROBLEM	(2) trail saw, crew of 3					
AREAS	(3) crew of 3					
MAJOR						
PROBLEM						
AREAS						
DISTANCES TO	490 yd mk3065 to mk3036					
MAJOR						
INTERSECTIONS						
Report prepared by:	St	teve Cobble	Asses	sment date:	02/02/08	3

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb) small blowdowns (sbd) culverts(cv) large blowdowns (lbd)

rolling dips (rd) rock work (rkw)

bridges (br) bridge building (bbd), ditches (dt) corrugated plastic(cp)

excessive erosion (ee) leaning tree (lt)) intersection marker(mk) dugout(du)

bog bridges (bb) culvert replacement (cr)

non-functioning(nf) functioning(fc)

damage(dg) not needed(nn) cm (corrugated metal)

rock stairs (rs) trail relocation (tr),

cribbing (cb) building new trail drainage (ntd)

retaining walls (rw) brushing needed (bn)

clay(cl)