

## TRAIL ASSESSMENT FORM

<b>Doc. #</b>		<b>Trail Name</b>	Ayer Trail	<b>Trail Type:</b>	Wide	<b>Condition</b>	Good
<b>Route:</b>	2094 – Skyline Trail – Tucker Hill Path 2072						
<b>Recent Weather:</b>	Sunny in the 50's						
<b>TRAIL LANDMARKS</b>	<ul style="list-style-type: none"> <li>• Trailhead is located on the west side of the Dark Hollow Path at Marker 2094.</li> <li>• Trail leaves from Marker 2094 headed northwest ascending at road width.</li> <li>• Athol Path crosses the Ayer Trail at .10 miles at the height of land.</li> <li>• Treadway begins descending.</li> <li>• Skyline Trail / Red Dot crosses Ayer Trail at .21 miles.</li> <li>• The Ayer Trail ends at Tucker Hill Path Marker 2072 at .24 miles</li> </ul>						
<b>MINOR PROBLEM AREAS</b>	(1) Evidence of drainage structure at .18 mi on L edge of trail. Should reestablish structure as trail is becoming very rocky due to erosion.						
<b>DISTANCES TO MAJOR INTERSECTIONS</b>	<ul style="list-style-type: none"> <li>• Dark Hollow Path Marker 2094 to Skyline Trail - .21 miles</li> <li>• Dark Hollow Path Marker 2094 to Tucker Hill Path - .24 miles</li> </ul>						
<b>Report prepared by:</b>	Bob Flagg			<b>Assessment date:</b>	4/24/16		