

TRAIL ASSESSMENT FORM

Doc. #	2012	Trail Name	Burnt Hill Path	Trail Type:	M(MTB)	Condition	Fair
Route:		From mk2085 crossing Angle Path at mk2092, heading generally north, to Bugbee Path at mk2111					
Recent Weather:		Clear and unseasonably dry					
TRAIL LANDMARKS		24yd nf wb, with a rd/dt that could use some clearing out(1) 82yd(mk2090 no mk Andover Trail) trail bears right. 176yd mk2092 Trail ascends steeply up Burnt Hill 269yd rd/wb needs cleaning(2) 286yd wb that could be converted to a rd(3) 389yd rd needs improving(4) 392yd rd needs improving(5) 630yd mk2111 trail ends at Bugbee Path					
MINOR PROBLEM AREAS		(1) cleanout (2) cleanout (3) possible rd construction (4) investigate possible rd improvement (5) investigate possible rd improvement					
MAJOR PROBLEM AREAS		With most of the trail being fall-line, proper drainage is badly needed					
DISTANCES TO MAJOR INTERSECTIONS		from mk2085 176yd to mk2092 630yd to mk2111					
Report prepared by:			Steve Cobble		Assessment date:		04/18/08

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)	
culverts(cv)	large blowdowns (lbd)	
rolling dips (rd)	rock work (rkw)	
bridges (br)	bridge building (bbd), ditches (dt)	corrugated plastic(cp)
excessive erosion (ee)	leaning tree (lt))	
intersection marker(mk)	dugout(du)	
bog bridges (bb)	culvert replacement (cr)	
non-functioning(nf)	functioning(fc)	
damage(dg)		
not needed(nn)		
cm (corrugated metal)		
rock stairs (rs)	trail relocation (tr),	
cribbing (cb)	building new trail drainage (ntd)	
retaining walls (rw)	brushing needed (bn)	
clay(cl)		
MTB(mountainbikes allowed)		
(mk2042) meaning not on DCR map		