TRAIL ASSESSMENT FORM

Doc. # 2013 Tra	il Name Angle	Path	Trail Type:	M(MTB)	Condition	Good
Route:		From mk2075 at Bugbee Path, heading generally south to mk2100 at Old				
		Rte 128				
Recent Weather:		Clear and unseasonably dry				
TRAIL	Wide trail sta	Wide trail starts at mk 2075 on the south side of Bugbee Path				
LANDMARKS	521yd mk209	521yd mk2092 int with Burnt Hill Path				
	598yd (2095)	598yd (2095)narrow path(Bolton Foot Path) on left				
	750yd mk210	750yd mk2100 no mk trail ends at Old Rte 128(1)(2)				
MINOR	(1) Instal	(1) Install mk				
PROBLEM						
AREAS						
MAJOR	(2)Where the	(2)Where the trail ends at Old Rte 128, the last 10yds descend sharply and				
PROBLEM		the tread is washing out onto the pavement. Investigate ways to alleviate				
AREAS	this, possibly	this, possibly with rockwork and/or re-routing				
DISTANCES TO	from mk2075	from mk2075				
MAJOR	521yd to mk2	521yd to mk2092				
INTERSECTION	S 750 yd to mk2	750yd to mk2100 trail end at Old Rte 128				
Report prepared by:	Steve Col	ble	Asses	sment date	: 04/18/08	8

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)				
culverts(cv)	large blowdowns (lbd)				
rolling dips (rd)	rock work (rkw)				
bridges (br)	bridge building (bbd), ditches (dt)	corrugated plastic(cp)			
excessive erosion (ee)	leaning tree (lt))				
intersection marker(mk) dugout(du)					
bog bridges (bb)	culvert replacement (cr)				
non-functioning(nf)	functioning(fc)				
damage(dg)					
not needed(nn)					
cm (corrugated metal)					
rock stairs (rs)	trail relocation (tr),				
cribbing (cb)	building new trail drainage (ntd)				
retaining walls (rw)	brushing needed (bn)				
clay(cl)					
MTB(mountainbikes allowed)					
(mk2042) meaning not on DCR map					