

TRAIL ASSESSMENT FORM

Doc. #	2017	Trail Name	(Rogue) Trail Between Top Tucker Hill and Headquarters Path	Trail Type:	N/A (not on any map)	Condition	Good
Route:		From the top of Tucker Hill/end of Athol Path, on a generally northerly direction, to Headquarters Path just east of 2112, on the green loop					
Recent Weather:		Clear and dry					
TRAIL LANDMARKS		Narrow, rocky path starts at the top of Tucker Hill 273yd natural wb helps with erosion 302yd end of trail at HQ Path					
MINOR PROBLEM AREAS		Only problem is that it is not on the map. This trail gets plenty of use, and is a good option.					
MAJOR PROBLEM AREAS							
DISTANCES TO MAJOR INTERSECTIONS		302yd end to end					
Report prepared by:			Steve Cobble		Assessment date:		05/12/08

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)	
culverts(cv)	large blowdowns (lbd)	
rolling dips (rd)	rock work (rkw)	
bridges (br)	bridge building (bbd), ditches (dt)	corrugated plastic(cp)
excessive erosion (ee)	leaning tree (lt))	
intersection marker(mk)	dugout(du)	
bog bridges (bb)	culvert replacement (cr)	
non-functioning(nf)	functioning(fc)	
damage(dg)		
not needed(nn)		
cm (corrugated metal)		
rock stairs (rs)	trail relocation (tr),	
cribbing (cb)	building new trail drainage (ntd)	
retaining walls (rw)	brushing needed (bn)	
clay(cl)		
MTB(mountainbikes allowed)		
(mk2042) meaning not on DCR map		