

# TRAIL ASSESSMENT FORM

<b>Doc. #</b>	2019	<b>Trail Name</b>	Prescott Foot Path (FBH)	<b>Trail Type:</b>	H	<b>Condition</b>	Good
<b>Route:</b>		From mk 2053 to (mk 2171) at top of picnic loop Part of the old Massachusuck trail					
<b>Recent Weather:</b>		clear and dry					
<b>TRAIL LANDMARKS</b>		Trail begins at mk 2053, at a 4x4 post with green dots on it. This trail was part of the old Massachusek trail. A steep, narrow technical ascent. 147yd sbd(1) 234yd some bn(2) 242yd Trail bears right towards picnic lot 262yd trail crosses pavement 279yd trail ends at base of Tucker Hill					
<b>MINOR PROBLEM AREAS</b>		(1) Chainsaw (2) bn					
<b>MAJOR PROBLEM AREAS</b>							
<b>DISTANCES TO MAJOR INTERSECTIONS</b>		From mk2053: 279yd to trail end					
<b>Report prepared by:</b>			Steve Cobble		<b>Assessment date:</b>		05/12/08

## Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb) culverts(cv) rolling dips (rd) bridges (br) excessive erosion (ee) intersection marker(mk) bog bridges (bb) non-functioning(nf) damage(dg) not needed(nn) cm ( corrugated metal) rock stairs (rs) cribbing (cb) retaining walls (rw) clay(cl) MTB(mountainbikes allowed) (mk2042) meaning not on DCR map	small blowdowns (sbd) large blowdowns (lbd) rock work (rkw) bridge building (bbd), ditches (dt) leaning tree (lt) dugout(du) culvert replacement (cr) functioning(fc)  trail relocation (tr), building new trail drainage (ntd) brushing needed (bn)
---	---

corrugated plastic(cp)