

TRAIL ASSESSMENT FORM

Doc. #	4023	Trail Name	Unnamed Trail Bunker Hill Rd 4235 to 4237	Trail Type:	Narrow - H	Condition	Good
Route:		Bunker Hill Road to 4237					
Recent Weather:		Rain last 24 hours					
TRAIL LANDMARKS		<ul style="list-style-type: none"> • Trailhead is located and leaves from the end of Bunker Hill Road at intersection marker 4235 at a series of boulders at road width. <ul style="list-style-type: none"> • Intersection marker 4235 in not noted on the latest DCR map 09/09. • Large grout pile located to the left of the treadway from the quarrying operations. • Treadway crosses over a section of the former Granite Railway at 175 feet and begins ascending slightly. • Bd crosses the treadway at 410 feet. Should be cut back to keep people from boot legging around it. (1) • Treadway begins to ascend the grout pile by way of newly installed granite steps at .1 miles. • Treadway enters an intersection with an unnamed path at intersection marker 4236 at .11 miles. Intersection marker has been defaced. (2) • Treadway leaves on the right leaving the intersection bordered by rkw to the right of the treadway and another set of granite steps at .12 miles. • Treadway enters another intersection with a road width path at .13 miles. At this point, UNT 4023 turns to the right. <ul style="list-style-type: none"> • Old intersection marker noted on tree and illegible. • Well test pointnoted to the right of the treadway at .19 miles • Treadway enters another intersection at a pond (Berry's Quarry) at .19 miles. • Unnamed Trail 4023 ends at this intersection at .19 miles. Intersection marker 4237 could not be located in the field (3). 					
MINOR PROBLEM AREAS		<ol style="list-style-type: none"> 1. Bd crosses the treadway at 410 feet. Should be cut back to keep people from boot legging around it. (1) 2. Treadway enters an intersection with an unnamed path at intersection marker 4236 at .11 miles. Intersection marker has been defaced. (2) 3. Unnamed Trail 4023 ends at this intersection at .19 miles. Intersection marker 4237 could not be located in the field (3). 					
MAJOR PROBLEM AREAS		<ul style="list-style-type: none"> • None Noted 					
DISTANCES TO MAJOR INTERSECTIONS		<ol style="list-style-type: none"> 1. Trailhead at intersection marker 4235 to 4237 - .19 miles 					
Report prepared by:			Ken Jones – 12/20/09		Assessment date:		12/15/09

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb)	small blowdowns (sbd)
culverts(cv)	large blowdowns (lbd)
rolling dips (rd)	rock work (rkw)
bridges (br)	bridge building (bbd),
bog bridges (bb)	culvert replacement (cr)
rock stairs (rs)	trail relocation (tr),
cribbing (cb)	building new trail drainage (ntd)
retaining walls (rw)	brushing needed (bn)
ditches (dt)	excessive erosion (ee)
	leaning tree (lt)