

Friends of the Blue Hills

Trail Volunteer Work Report

Work date (mm/dd/yy): 7/7/09

Report date: 7/7/09

Your name: Dave Humphreys

List Volunteers working with you:

Jackson and Aidan Humphreys

Trail Name: Border Path

Section Name/Description:

Between 1100 and 1135

Work Completed (Please be specific with location of work. Note hazards & potential hazards addressed if applicable):

Cleared all waterbars of debris. Dug out and re-established waterbars where washed out. All waterbars on this section are now established and functional.

Total Hours (# of people x hours worked): 4.00

Work Remaining:

Waterbar at base of 1135 needs significant upgrade which will some time and repeated visits. No big deal

Other comments (areas of concern, wildlife sightings, trail markings and signage condition, need for re-route, possible encroachment):

Outside of my area of operation between 1135 and 1140 (Green Dot) I observed what appears to be a newly constructed waterbar consisting of a pile of rocks with sticks placed on top that does not conform (in my opinion) to the standards and practices of proper trail maintenance and could be very hazardous to mountain bikers at night. Insofar as this was observed outside of my area, I left it in place. Next time, I'll have a camera with me.

Forward completed electronic form to: Dexter Robinson @ dexpcdoc@gmail.com