

Friends of the Blue Hills

Trail Volunteer Work Report

Work date (mm/dd/yy): 10/25/09

Report date: 10/25/09

Your name: Ray Ajemian

List Volunteers working with you:

0

Trail Name: Border Path

Section Name/Description:

1175 to Unquity Road

Work Completed (Please be specific with location of work. Note hazards & potential hazards addressed if applicable):

Worked on six water bars. Dug them out the width of the path and built them up

Observed water going through culverts.

Total Hours (# of people x hours worked): 1.00

Work Remaining:

Possible more work. See below

Other comments (areas of concern, wildlife sightings, trail markings and signage condition, need for re-route, possible encroachment):

Water from the left of the path at Marker 1175 (walking the Border Path toward Unquity Rd) comes onto the path and flows down the path to the next water bar. At that point part of the water flows into the stream and part goes over the water bar and works its way down to the second bar. (I observed this after a heavy rain.) If one wants to keep water off the path, there would be major work needed to get it to go over the stream. Note at that intersection an awful lot of water is entering the path.

Further down the path water also enters from the left and works its way down the left side of the path before hitting water bar number four. It seems to be working, but again there is the issue of whether it should be left alone or a new water bar built where the water hits the trail.

Forward completed electronic form to: Dexter Robinson @ dexpcdoc@gmail.com