Friends of the Blue Hills

Trail Volunteer Work Report

Work Date:5/18/0	8	Report date:	_5/18/08
Your name:Robe	rt Flagg		
List Volunteers working			
Trail Name:Laure			
Section Name/Descrip	tion:Worked	at the intersection	of 3121
Work Completed (Plea & potential hazards ad	•		. Note hazards
Culvert on up-stream	nside was complet	ely buried under le	eaves and dirt and
down-stream almost	buried. Drainage	ditch outflow fille	ed with leaves and
the level slopes up to	oward a tree block	ing the ditch. Ope	ened the up-stream
side and cleared out	the outflow draina	age ditch on the do	wn-stream side.
Total Work Hours:	_3 hours		
Work remaining:U	o-stream side coul	d be dug out furth	er and the outflow
ditch could use addi	tional digging to	improve the slope.	There is a medium
size blow-down that	must be removed	l to improve the ou	atflow slope.
Other comments: (area condition, need for re-			l markings and signage
none			

Forward completed electronic form to: Dexter Robinson @ dexpedoc@hotmail.com Or mail to Dexter at 227 Winter Street, Hanson, MA 02341