

Friends of the Blue Hills

Trail Volunteer Work Report

Work date (mm/dd/yy): 6/6/10

Report date: 06/06/10

Your name: Ray Ajemian

List Volunteers working with you:

0

Trail Name: Border Path

Section Name/Description:

1175 to Unquity Road

Work Completed (Please be specific with location of work. Note hazards & potential hazards addressed if applicable):

survey path

Total Hours (# of people x hours worked): 0.00

Work Remaining:

. See below

Other comments (areas of concern, wildlife sightings, trail markings and signage condition, need for re-route, possible encroachment):

Path is in good shape. There is a small section where the path narrows, which I will shortly clear, but it is really not an issue.

The possible issue is the runoff from 1175 down the path to the next two to three water bars. There is so much water that goes down the path in heavy rains that the first water bar can't handle it. In order to decrease the runoff major work would have to be done at 1175 to funnel the water elsewhere - not a simple solution.

Forward completed electronic form to: Dexter Robinson @ dexpdoc@gmail.com