

TRAIL ASSESSMENT FORM

Doc. #	1005	Trail Name	Wildcat Notch Path	Trail Type:	Wide - M	Condition	Good
Route:		Hillside Street – 1086 – 1093 – 1083 – 1092 – 1103 – 1115 – Wolcott Path					
Recent Weather:		Dry for past several days, Sunny - ± 85°F					
TRAIL LANDMARKS		See original report.					
MINOR PROBLEM AREAS		<ul style="list-style-type: none"> Brushing required at trailhead. Minor maintenance work and general cleaning of grade reversals (typical most grade reversals). Culverts cleaning at the area of 1083. 					
MAJOR PROBLEM AREAS		<ul style="list-style-type: none"> Need new grade reversal about 100 yards south of the (new) southern junction with the Skyline Trail. Need gravel/soil to cover exposed stones at the south (down) side of the new grade reversal that was built last year between Half Way Path and Skyline. 					
DISTANCES TO MAJOR INTERSECTIONS		See original report.					
Report prepared by:			Amir Degany		Assessment date:		July 5, 2010

Abbreviations:

Usage type: foot traffic only (H), multi-use (M)

waterbars (wb) culverts(cv) rolling dips (rd) bridges (br) bog bridges (bb) rock stairs (rs) cribbing (cb) retaining walls (rw) ditches (dt)	small blowdowns (sbd) large blowdowns (lbd) rock work (rkw) bridge building (bbd), culvert replacement (cr) trail relocation (tr), building new trail drainage (ntd) brushing needed (bn) excessive erosion (ee) leaning tree (lt)
--	---

V5 NDR