

TRAIL ASSESSMENT FORM

Doc. #		Trail Name	Curve Path	Trail Type:	M	Condition	Good
Route:		Mk 3130 at Bouncing Brook Path to 3153 at Wampatuck Path .37 mi					
Recent Weather:		Overcast, no precipitation past 7 days					
TRAIL LANDMARKS		mk3130 4' wide trail 40 yds. telephone pole waterbar, exposed, R to L, clean 68 yds. telephone pole waterbreak 70 yds. telephone pole waterbreak 85 yds. telephone pole waterbreak 125 yds. telephone pole waterbreak 130 yds. telephone pole waterbreak 164 yds. telephone pole waterbreak 174 yds. 18" black plastic culvert, R to L, stone surround, exposed, small brook running thru it 184 yds. telephone pole waterbar, L to R, all set 214 yds. Marker 3135 intersection with Sassaman Notch Path on NW side. Curve Trail starts NE bearing and trail widens. 404 yds. Marker 3143 'triangle' intersection with Squamaug Notch Path. Trail turns left at triangle, and quick right, after triangle. Some washout coming down from N off Squamaug Notch Path, corrected with new grade reversal on Squamaug. Follows a perennially wet area on South side 659 yds. Marker 3153 intersection w/ Wampatuck Path					
MINOR & MAJOR PROBLEM AREAS		None					
DISTANCES TO MAJOR INTERSECTIONS		<ul style="list-style-type: none"> Bouncing Brook Path Marker 3130 to Sassaman Notch Path Marker 3135 - 214 yds. Bouncing Brook Path Marker 3130 to Squamaug Notch Path - 404 yds. Bouncing Brook Path Marker 3130 to Wampatuck Path Marker 3153 - 659 yds. 					
Report prepared by:		Bob Flagg			Assessment date:		01/9/16