

Friends of the Blue Hills

Trail Volunteer Work Report

Work date (mm/dd/yy): 6/28/09

Report date: 6/28/09

Your name: Bob Flagg

List Volunteers working with you:

Trail Name: South Skyline

Section Name/Description:

Hillside St to intersection with Coon Hollow Path (Marker 1123)

Work Completed (Please be specific with location of work. Note hazards & potential hazards addressed if applicable):

Brushed trail including removal of a number of branches overhanging trail, cleaned several waterbars and picked up small bag of trash along the way. Improved flow of water off the trail in several locations.

Total Hours (# of people x hours worked): 4.00

Work Remaining:

Trail heading up Houghton Hill is steep and has erosion problems in many areas. Probably need to add steps or water breaks to stabilize the trail. Near the top of Houghtons Hill, there were a couple steps added but people are leaving the trail to the South of the trail. There is a small rotting bridge where the trail crosses Conn Hollow Brook (near Marker 1123) that needs to be replaced. Will write up construction summary.

Other comments (areas of concern, wildlife sightings, trail markings and signage condition, need for re-route, possible encroachment):

Forward completed electronic form to: Dexter Robinson @ dexpdoc@hotmail.com