TRAIL ASSESSMENT FORM

Doc. #	Trail Na	me	Chickadee Path	Trail Type:	Wide	Condition	Good
·							
Route:		Northeast from intersection 1072 on Summit Road					
Recent Weather: S		Sunny, 45°F, all day rain on previous day					
TRAIL		• 41 ft trail forks to right (unnamed/mapped)					
LANDMARKS		Some brushing needed					
		• 178ft Water trail in middle of path					
		• 302ft Grade reversal – simple cleaning but good shape					
		• 492ft grade reversal – great shape					
		• 0.12mi grade reversal – needs some maintenance but good					
		• 0.13mi end of trail with Puddle Path					
MINOR PROBLEM		•	Some brushing, som	e cleaning of g	rade reversa	ıls	
AREAS							
MAJOR							
PROBLEM							
AREAS							
DISTANCES TO		• Oft – Intersection 1072 with Summit Road					
MAJOR		• 0.13mi – Ends at Puddle Path just south of Intersection 1085					
INTERSECT	TIONS						
Report prepared by:		R	obert Shine	Asses	sment date	: 10-23-20)16