

TRAIL ASSESSMENT FORM

Doc. #		Trail Name	Eliot Path	Trail Type:	Footpath	Condition	Good
Route:	Eliot Circle Marker 1055 – 1051 - Rt 28 Marker 1023						
Recent Weather:	Warm, 50's - melting snow and ice – Snow cover on trail less than 1 inch. Trail a bit muddy from snow melt.						
TRAIL LANDMARKS	<ul style="list-style-type: none"> • Trail starts at Eliot Circle Marker 1055. Granite post marked Trailside Museum. Trail part of Red Dot Loop. Two railroad tie waterbreaks at start of trail. • Trail is very uneven with lots of rocks and ledges. Hard to follow in some places as trail is braided following different paths. • Railroad tie stairs at .02 miles. • Summit Road Marker 1051 crosses trail at .25 miles. Bike sign and sign for summit. • Stairs running downhill after crossing guardrail at Summit Road. • Small trail crosses trail at .28 miles. • Trail very ledgy for about .15 miles with some steps and stone waterbreaks. • Large board waterbar, L to R, at .45 miles. • Trail joins with other side of Red Dot Loop at .45 miles. • Series of steps from .45 to .47 miles. • Granite curb steps from .47miles to end of trail. • Trailhead ends at South parking lot on Rt 28 at Marker 1023 at .50 miles. Trail part of Red Dot Loop. Granite post at trailhead and kiosk. 						
MINOR&MAJOR PROBLEM AREAS	None						
DISTANCES TO MAJOR INTERSECTIONS	<ul style="list-style-type: none"> • Eliot Circle Marker 1055 to Summit Road Marker 1051 – .25 miles. • Eliot Circle Marker 1055 to South parking lot Marker 1023 – .50 miles. 						
Report prepared by:	Bob Flagg			Assessment date:	2/2/16		