

TRAIL ASSESSMENT FORM

Doc. #		Trail Name	Fells Path	Trail Type:	Medium	Condition	Good
Route:	Buck Hill Trail Marker 2152, heading generally S, Bugbee Path Marker 2140						
Recent Weather:	Overcast, 60's, some rain 24 hours ago						
TRAIL LANDMARKS	<ul style="list-style-type: none"> • Medium width trail begins at Buck Hill Trail Marker 2152. Perennially wet area with wetlands upslope and to the right of trail. • 10 yds swale, L to R, carries water from trench upslope under Buck Hill Trail from small wetlands area. Need to clean upslope trench and swale. • 60 yds swale, L to R • 100 yds knick on R • 150 yds digout on L • 302 yds Pig Rock Path Marker 2149 enters on L. Trail bears right. • 474 yds Trail ends at Bugbee Path Marker 2140. 						
MINOR&MAJOR PROBLEM AREAS	None						
DISTANCES TO MAJOR INTERSECTIONS	<ul style="list-style-type: none"> • Buck Hill Trail Marker 2152 to Bugbee Path Marker 2140 - 474 yds 						
Report prepared by:	Bob Flagg			Assessment date:	4/1/16		