## TRAIL ASSESSMENT FORM

Doc. # Trail N	Name	Old Route 128	Trail Type:	Road	Condition	Good
				1	•	
Route:	Houghtons Pond Athletic Field gate to Monatiquot Path					
<b>Recent Weather:</b>	Sunny in the 50's					
TRAIL	• Trailhead is located at the gate at the end of the road that leads to					
TRAIL LANDMARKS	<ul> <li>Trainlead is located at the gate at the end of the fload that leads to the Athletic Fields near Houghton's Pond. Trail is the old roadbed for Route 128. New Comfort Station located at trailhead.</li> <li>Trail leaves from L at 507 feet and runs toward Houghton's Pond.</li> <li>Roadbed of asphalt starts at 537 feet.</li> <li>Culvert crossed under road at .16 miles. Stone surround 18" concrete culvert, L to R. Nice outcropping of pudding stone at trailside. Spur trail to Andover Path.</li> <li>Burnt Hill Path Marker 2085 enters left at .31 miles.</li> <li>Culvert at .36 miles (relatively dry) probably flows at high water.</li> <li>Angle Path enters left at Marker 2100 at .47 miles.</li> <li>Brook flowing through culvert at .69 miles. 18" concrete culvert.</li> <li>Spur trail to Beech Hollow Path enters left at Marker 2146 at .78 miles. Path</li> </ul>					
MINOR&MAJOR PROBLEM AREAS	None					
DISTANCES TO	• Trailhead to Burnt Hill Path Marker 2085 at .31 miles					
MAJOR	• Trailhead to Angle Path Marker 2100 at .47 miles					
INTERSECTIONS	•	• Trailhead to Beech Hollow Path Marker 2146 at .78 miles				
	•	Trailhead to Oblique Path Marker 2150 at .88 miles				
	•	Trailhead to Monatiquot Path at 1.00 miles				
<b>Report prepared by:</b>	B	ob Flagg	Asses	sment dat	<b>e:</b> 4/24/16	